

Annexure D

BUILDING SAFETY CERTIFICATE

No. 120 / Comp AE-IV/26

Dated: 02/09/2026

It is certified that the existing building CMS Public School
building or premises) at Mitthauli, Mathura (name of the

(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1	X	X	X	X	X

The building is owned/occupied by CMS Public School, Mitthauli Mathura (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public works department (Name of Department/ Govt.) on 02/9/2026 (date of inspection) in the presence of Harendra Singh, Manager CMS Public School (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 02/9/26 for a period of 02 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The structure safety certificate dated 15/5/26 issued by
2. Architect Saurabh Saxena Reg no - A 9100195-05 1887 Gali
3. Ganga dayal Mandi Ramdas, Mathura should be considered as the
4. Part of this certificate.

Issued on 02/09/26 at Mathura by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name : Bojresh Kumar Sharma

Designation : सहायक अभियन्ता

Name & Address of Department Office - 1, लो० नि० वि० मथुरा

Principal
C.M.S. PUBLIC SCHOOL
MITTHAULI (MATHURA)

Manager
C.M.S. Public School
Mitthauli (Mathura)